

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD

MPP

Date: 09.03.06	Job No.: P00252	ADR Yes/No: Yes	ADR Date: 09.03.06	ECN #: 09- 541
Product No.: D130-780	Created By: HS	Approved By: <i>M/S</i>		
Product Name: Spacepod, Hinge Door Modification		Checked By:	General Manager Approval:	

Distribution	Reqd	Resp	Initial / Date	Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL		DQA / QA Coord	N		
Production Engineering Coord	Y	EC		QC Coordinator	N		
Production Document Control	Y	JLB		Marketing	Y	SW	
Customer Technical Support	Y	DS		Customer Order Processing	N		

Reason for Change:
Door seal receives excessive wear from hinge door modification - provides replacement seal

Documents Affected:
DSI 9444 Rev. A
D3892 Rev. A

PARTS MUST COMPLY ☐ PREVIOUS PARTS SATISFACTORY ☒

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N		No kits in the field	
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09.03.10 <i>HS</i>
10	Update Controlled PDF Files	Y	KJ		09.03.10 <i>HS</i>
11	Update Master Document List (MDL)	Y	HS	Rev. D	09.03.08 <i>HS</i>
12	Update Document Record (DR)	Y	KJ	Rev. B	09.03.10 <i>HS</i>
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	Y	KJ		09.03.10 <i>HS</i>
16	Update / Verify ARC Database	Y	KJ		09.03.10 <i>HS</i>
17	Create / Update Change Record Form	Y	KJ	D130-780-011 still at CHG 001	09.03.10 <i>HS</i>
18	Create / Update PPP's	Y	KJ		09.03.10 <i>HS</i>
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ	add ADR	09.03.10 <i>HS</i>
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.03.10 <i>HS</i>
22					
23					

Description / Action:
The Hinge door modification D130-780-011 causes wear to the upper door seal. DSI 9444 provides instructions for the installation of D3892-1 replacement seal.

Create estimates for the production of D3892-1 seals.

- No kits in stock
- Add 1x D3892-1 to D130-780-011 kits in production *add to Wlo's 45530 45531 45532*
- HS will take care of D130-780-011 currently being installed at Eagle Copters.
- DSI 9444-011 @ CHG 001

09-03-23

ECN Verified & Complete: _____ Date: _____

ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

mpp

Date: 09.03.06	Job No.: P00252	ADR Yes/No: Yes	ADR Date: 09.03.06	ECN #: 09- 541
Product No.: D130-780	Created By: HS	Approved By: <i>[Signature]</i>		
Product Name: Spacepod, Hinge Door Modification		Checked By:	General Manager Approval:	

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	
Production Engineering Coord	Y	EC	
Production Document Control	Y	HS <i>JLB</i>	<i>JLB</i>
Customer Technical Support	Y	DS	

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	N		
QC Coordinator	N		
Marketing	Y	SW	
Customer Order Processing	N		

Reason for Change:
Door seal receives excessive wear from hinge door modification - provides replacement seal

Documents Affected:
DSI 9444 Rev. A
D3892 Rev. A

PARTS MUST COMPLY ☐ PREVIOUS PARTS SATISFACTORY ☒

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N		No kits in the field	
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09.03.10 <i>[Signature]</i>
10	Update Controlled PDF Files	Y	KJ		09.03.10 <i>[Signature]</i>
11	Update Master Document List (MDL)	Y	HS	Rev. D	09.03.08 <i>[Signature]</i>
12	Update Document Record (DR)	Y	KJ	Rev. B	09.03.10 <i>[Signature]</i>
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	Y	KJ		09.03.10 <i>[Signature]</i>
16	Update / Verify ARC Database	Y	KJ		09.03.10 <i>[Signature]</i>
17	Create / Update Change Record Form	Y	KJ	D130-780-011 still at CHG 001	09.03.10 <i>[Signature]</i>
18	Create / Update PPP's	Y	KJ		09.03.10 <i>[Signature]</i>
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ	add ADR	09.03.10 <i>[Signature]</i>
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.03.10 <i>[Signature]</i>
22					
23					

Description / Action:
The Hinge door modification D130-780-011 causes wear to the upper door seal. DSI 9444 provides instructions for the installation of D3892-1 replacement seal.

- Create estimates for the production of D3892-1 seals.
- No kits in stock
- Add 1x D3892-1 to D130-780-011 kits in production
- HS will take care of D130-780-011 currently being installed at Eagle Copters.
- DSI 9444-011 @ CHG 001

45530
45531
45532
09.03.10

ECN Verified & Complete: _____ Date: _____